## COMPANY PROFILE



## **DESIGN AND CONSULTANCY SERVICES**

## **Chittagong Office:**

581/A, Mehedibag (Beside of National Hospital) Panchlaish, Chattogram, Bangladesh.

TELEPHONE:+88-01711954447; +8801710062256

E-mail: e.hasan1977@ymail.com, info@dcsgroupbd.com

#### **Muhammad Enamul Hasan**

B. Sc Engineer (Mechanical)

Chief Executive Officer

MIEB- 23266, CDA Reg.No-0336/2014

Design and Consultancy Services (DCS)

581/A, Mehedibag (Beside of National Hospital)

Panchlaish, Chattogram, Bangladesh. Tel: +88-01711954447; +8801710062256

E-mail: e.hasan1977@ymail.com

**Chittagong Office:** 581/A, Mehedibag (Beside of National Hospital) Panchlaish, Chattogram, Bangladesh Phone:+88-01711954447; +8801710062256,E-mail: <a href="mailto:e.hasan1977@ymail.com">e.hasan1977@ymail.com</a>; <a href="mailto:info@dcsgroupbd.com">info@dcsgroupbd.com</a>

#### Introduction

DESIGN & CONSULTANCY SERVICES (DCS) is a prominent multi-disciplinary consulting organization having well-known, experienced and qualified engineers and personnel of various disciplines. DCS has been formed to provide specific consulting services of Detailed Engineering Assessment (Fire & Electrical) .DCS has the capability of managing, designing, estimating, preparing schedule ,Installation & supervising of electro-mechanical work of different industries, RMG, pharmaceuticals, Luxury Hotels & Restaurants, High-rise multipurpose Commercial buildings, Shopping complexes, Apartment building etc.

The Company Started operation in <u>January 2014</u>this has grown to become one of the leading technically Centre for the field of Detailed Engineering Assessment (Fire & Electrical)

#### **SCOPE OF SERVICES**

#### **Detail Engineering Fire.**

- (i) Fire system Assessment & Consultancy: as per NFPA & BNBC.
  - a. Fire Hydrant systems assessment.
  - b. Fire Detection systems assessment.
  - c. Fire Protection systems assessment.
  - d. Fire Sprinkler systems assessment.
  - e. Fire door layout assessment.
  - f. Fire rated construction assessment.

#### (ii) Fire system Design:

- a. Fire Hydrant systems design as per NFPA-14 & BNBC.
- b. Fire Detection systems design as per NFPA-72 & BNBC.
- c. Fire Sprinkler systems design as per NFPA-13 & BNBC.
- d. Fire door layout as per NFPA-80& BNBC.
- e. Fire extinguish layout as per NFPA-10 & BNBC.

#### (iii) Fire system Installation, Supervision, Rectification Maintenance:

- a. Fire Hydrant systems installation, supervision, rectification& maintenance as per NFPA-20, NFPA-22, NFPA-24, NFPA-25 & BNBC.
- b. Fire Detection systems, supervision, rectification & maintenance As perNFPA-72 & BNBC.
- c. Fire Sprinkler systems, supervision, rectification & maintenance as per NFPA-13 & BNBC.
- d. Fire door installation &maintenance as per NFPA-10 & BNBC.

#### (iv) Fire system Test Documentation & Training:

- a. Fire Hydrant systems test ,documentation & training as per NFPA-25 & BNBC.
- b. Fire Detection systems test, documentation& training as perNFPA-13 BNBC.
- c. Fire Sprinkler systems test, documentation& training as per NFPA-13 &BNBC.
- d. Emergency light test & documentation.
- e. Exit light test & documentation.
- f. Sound Test & documentation
- g. Documentation on Housekeeping as per Alliance Fire Safety Standard
- h. Documentation Hot working as per NFPA-51B.
- i. Fire Drills conduct as per BNBC Part 4 Appendix A.
- j. Life safety as per NFPA 101.

#### **Detail Engineering Electrical.**

## (i) Electrical system Assessment & Consultancy: As per NFPA &BNBC

- a. Single Line Diagram (SLD) assessment.
- b. Electrical Layout Diagram (ELD) assessment.
- c. Lightning Protection systems assessment.
- d. Earthling Layout assessment.

#### (ii) Electrical system Design: As per NFPA &BNBC

- a. Single Line Diagram (SLD).
- b. Electrical Layout Diagram (ELD).
- c. Lightning Protection systems Design.
- d. Earthling Layout.

#### (iii) Electrical system Execution, Supervision & Rectification: As per NFPA & BNBC

- a. Single Line Diagram (SLD) Execution, Supervision & Rectification.
- b. Electrical Layout Diagram (ELD) Execution, Supervision & Rectification.
- c. Lightning Protection systems Execution, Supervision & Rectification.
- d. Earthling Layout Execution, Supervision & Rectification.

#### (iv) Electrical system Test, Documentation & Training: As per NFPA &BNBC.

- a. Thermography Scan with report.
- b. System Earth Resistance (ER) Test.
- c. Insulation Resistance (IR) Test.
- d. LPS Earth Resistance (ER) Test.
- e. Electrical Safety Training.

#### LIST OF KEY PERSONNEL OF THE COMPANY:

## **Expertise on Fire**

SI. No	Name	Qualification	Position	Total Experienc e	Experience DEA Fire
1.	Engr. Dr. Jamal Uddin Ahmed	B.Sc.Engg. in Mechanical (CUET). M.Sc.Engg.in Mechanical (BUET). Phd(UM MALAYSIA).	Adviser	20 years	8 years
2.	Engr. Md. Enamul Hasan	B.Sc.Engg. in Mechanical (MIEB-23266)	CEO	10 years	6 years
3.	Engr. Md. Mamunur Rashid	B.Sc.Engg. in Mechanical	Project Manager	5years	4 years
4.	Engr. Md. Minhazul Islam	B.Sc.Engg. in EEE(UITS)	Project Manager	4 years	3 years

## **Expertise on Electrical**

SI. No.	Name	Qualification	Position	Total Experience	Experience DEA Electrical
1.	Engr. AMM Mostafizur Rahman	B.Sc.Engg. in EEE (RUET).	Chief Consultant	10 years	05 years
2.	Engr. Md. Mamorej Hossen	B.Sc.Engg. in EEE(UITS)	COO	05 years	05 years
3.	Engr. Md. Abdul Rakib	B.Sc.Engg. in EEE(UITS)	Project Manager	05 years	05 years
4.	Engr. Md. Robiul Islam	B.Sc.Engg. in EEE(UITS)	Executive Engineer	05 years	05 years
5.	Engr. Md. Hafizur Rahman	B.Sc.Engg. in EEE(UITS)	Executive Engineer	03 years	03 years

## **Detail Engineering Fire, Project List**

**Fire Safety Assessment:** Under Banner of Shaheedullah & Uttaron Technologies. LEAD assessor Fire: Engr. Muhammad Enamul Hasan.

Sl.	Factory Name	Factory Address	Description of Job &	Status of the
No	•	•	Responsibility	project
	Shamsher Rezia Fashions	(10-storied Commercial	Initial Fire Safety	Report
1.	Ltd.	Building).CHA-72/1/C	Assessment For ALLIANCE.	Completed on
		Progati Šhawrani Uttar Badda.Dhaka	LEAD assessor Fire.	27 Feb 2014.
	SMART JACKET (BD)	Plot: 13, Sector: 1/A, road	Initial Fire Safety	Report
2.	LTD.	:5 CEPZ. Chittagong	Assessment For ALLIANCE.	Completed on
			LEAD assessor Fire	02 Nov 2013.
	MAM APPAREL &	Tower, 3233/B,	Initial Fire Safety	Report
3.	TEXTILES LTD,MAM	Loharpool, Saraypara,	Assessment For ALLIANCE.	Completed on
		Pahartali,Ctg	LEAD assessor Fire	20 May 2014
	<b>Envoy Textiles Ltd,</b>	Jamirdia, Bhaluka,	Initial Fire Safety	Report
4.		Mymensingh Dhaka	Assessment For ALLIANCE.	Completed on
			LEAD assessor Fire	02 Feb 2014.
	GLOBAL TROUSERS	11, Kalughat Heavy	Initial Fire Safety	Report
5.	LTD	Industrial Area	Assessment For ALLIANCE.	Completed on
	•	Chittagong	LEAD assessor Fire	17 May 2014
	Karnaphuli Shoes	Anowara, Plot # G1 and	Initial Fire Safety	Report
6.	Industries Ltd	G2, Korean EPZ,	Assessment For ALLIANCE.	Completed on
		Chittagong	LEAD assessor Fire	27 Mar 2014
	DESH GARMENTS	53/A Kalurghat Heavy	Initial Fire Safety	Report
7.	LIMITED,	Industrial Area	Assessment For ALLIANCE.	Completed on
		Kalurghat, Chittagong	LEAD assessor Fire	14 May 2014
	H.B. Fashions Ltd,	590 Colonel Jones Road,	Initial Fire Safety	Report
8.		North Kattali,	Assessment For ALLIANCE.	Completed on
		Pahartali, Chittagong	LEAD assessor Fire	18 Jun 2014
	HKC Apparels Ltd.	2&5 FL, 1170/B,	Initial Fire Safety	Report
9.		ShahamanatShetu RD	Assessment For ALLIANCE.	Completed on
7.		East Sholashahar,	LEAD assessor Fire	29 Mar 2014
		Bahaddarhat, Chittagong.		
	Savannah Fashion Ltd.	1170/B-1, Shah	Initial Fire Safety	Report
10.		AmanantShetu Road	Assessment For ALLIANCE.	Completed on
10.		East Sholashahar,	LEAD assessor Fire	29 Mar 2014
		Bahaddarhat, Chittagong		

## Fire System Design:

Design By: Engr. Muhammad Enamul Hasan.

Sl.	FactoryName	Factory Address	Description of Job	Status of the project
No				
11.	Familytex (BD) Limited.	Plot 47-48, Road 5, Sector 4, CEPZ, Chittagong.	Fire Hydrant systems design.	-Design Completed & Approved by ALLIANCE

12.	Premier 1888 Ltd.	41-47 & 84, Sector # 7, EPZ, Chittagong Bangladesh	Fire Hydrant systems design.  Fire Detection systems design	-Design Completed & Approved by ALLIANCE
13.	MAM APPAREL &TEXTILES LTD,MAM	Tower, 3233/B, Loharpool, Saraypara, Pahartali,Ctg	Fire Detection systems design	-Design Completed &Approved by ALLIANCE
14.	CROWN MILLS (BD) LTD.	Plot No. 17-19 & 36-38, Sector 2,CEPZ Chittagong	Fire Hydrant systems design.  Fire Detection systems design	-Design Completed & Approved by ALLIANCE
15.	MZM (CEPZ) LTD.	Plot # 8-9, Sector # 2/A, CEPZ, Chittagong	Fire Hydrant systems design. Fire Detection systems design	-Design Completed & Approved by ACCORD
16.	Need Tex CTG Ltd.	154/C Rajakhal Road, East Bakalla, Chittagong.	Fire Hydrant systems design.  Fire Detection systems design	-Design Completed & Approved by ALLIANCE
17.	HELA CLOTHING BANGLADESH LTD.	Plot # 53, 54, 66, 67; Sector # 01, Karnaphuli EPZ, Chittagong, Bangladesh.	Fire Sprinkler systems design Fire Hydrant systems design. Fire Detection systems design	-Design Completed & Approved by ACCORD
18.	SIAM'S SUPERIOR LTD. (UNIT-1).	Plot # 6-8 Sector # 01, CEPZ, Chittagong, Bangladesh	Fire Hydrant systems design. Fire Detection systems design	-Design Completed & Approved by ALLIANCE
19.	SIAM'S SUPERIOR LTD. (UNIT-2)	Plot # 7-9 Sector # 08, CEPZ, Chittagong, Bangladesh	Fire Detection systems design	-Design Completed & Approved by ALLIANCE
20.	Legacy Fashion Ltd.	BSCIC, Kalurghat, Chittagong, Bangladesh	Fire Hydrant systems design.  Fire Detection systems design	-Design Completed & Approved by ALLIANCE
21.	Anowara Fashion Ltd.	BSCIC, Kalurghat, Chittagong, Bangladesh	Fire Hydrant systems design.  Fire Detection systems design	-Design Completed & Approved by ALLIANCE

## Fire System: Material supply, Installation, Supervision, Test, Commissioning & Maintenance:

LEAD by: Engr. Muhammad Enamul Hasan

Sl.	FactoryName&	Factory Address	Description of Job	Status of the project
No	Contact Per Ref	-	_	
22.	SIAM'S SUPERIOR LTD. (UNIT-2)  Contact Per Ref Mr. Didarul Islam GM HR & Compliance 01977701191	Plot # 7-9 Sector # 08, CEPZ, Chittagong, Bangladesh	Fire Hydrant systems Installation with material Supply, Supervision, Test & Commission.  Fire Detection systems Installation with material supply, Supervision, Test & Commission.	-Installation Completed & Approved by ALLIANCE
23.	MZM (CEPZ) LTD.  Contact Per Ref Mr. Masud GM HR & Compliance 01755596603	Plot # 8-9, Sector # 2/A, CEPZ, Chittagong	Fire Detection systems Installation Supply, Supervision, TestCommission.	-Installation Completed & Approved by ACCORD
24.	CROWN MILLS (BD) LTD  Contact Per Ref Mr. Taimur GM HR & Compliance 01722099343	Plot No. 17-19 & 36-38, Sector 2,CEPZ Chittagong	Fire Detection systems Installation with material Supply, Supervision, Test &Commission	-Installation Completed & Approved by ALLIANCE
25.	Premier 1888 Ltd.  Contact Per Ref Mr. Taimur GM HR & Compliance 01722099343	41-47 & 84, Sector # 7, EPZ, Chittagong Bangladesh	Fire Hydrant systems Installation with material Supply, Supervision, Test &Commission	-Installation Completed & Approved by ALLIANCE
26.	Need Tex CTG Ltd.  Contact Per Ref Mr. Hannan Managing director 01819311799	154/C Rajakhal Road, East Bakalla, Chittagong.	Fire Detection systems Installation with material Supply, Supervision, Test Commission.	-Installation Completed & Approved by ALLIANCE
27.	HELA CLOTHING BANGLADESH LTD. Contact Per Ref Mr. Didarul Islam GM HR & Compliance 01977701191	Plot # 53, 54, 66, 67; Sector # 01, Karnaphuli EPZ, Chittagong, Bangladesh.	Fire Hydrant, Detection &Sprinkler systems Installation with material Supply, Supervision, TestCommission.	-Installation going on.
28.	SIAM'S SUPERIOR LTD. (UNIT-1).	Plot # 6-8 Sector # 01, CEPZ, Chittagong,	Fire Hydrant systems Installation with	-InstallationCompleted & Approved by



	Contact Per Ref Mr. Didarul Islam GM HR & Compliance 01977701191	Bangladesh	material supply, Supervision, Test & Commission.  Fire Detection systems Installation with material supply, Supervision, Test & Commission	ALLIANCE
29.	Contact Per Ref Mr. Helal Uddin GM HR & Compliance 01919648258	BSCIC, Kalurghat, Chittagong, Bangladesh	Fire Hydrant systems Installation with materialsupply, Supervision, Test &Commission.  Fire Detection systems Installation with material supply, Supervision, Test & Commission	-Installation Completed & Approved by ALLIANCE
30.	Anowara Fashion Ltd.  Contact Per Ref Mr. Helal Uddin GM HR & Compliance 01919648258	BSCIC, Kalurghat, Chittagong, Bangladesh	Fire Hydrant systems Installation with material supply, Supervision, Test &Commission. Fire Detection systems Installation with material supply, Supervision, Test & Commission	-Installation Completed & Approved by ALLIANCE
31	Hemple Rhee Mfg. Co. (BD) Ltd.  Contact Per Ref Mr. Mohiuddin GM 01711159142	Plot#23-24, Sector-6, CEPZ, and Chittagong, Bangladesh.	Fire Hydrant& sprinkles systems Installation with material supply, Supervision, Test &Commission. Fire Detection systems Installation with material supply, Supervision, Test & Commission	-Installationgoing on.
32.	BD Designs Private Ltd. Contact Per Ref Mr. Shahbuddin Managing director 017133311827	Address: Plot No. 48-49, Sector-3, KarnaphuliEPZ ,Chittagong,Banglad esh.	Fire Hydrant& sprinkles systems Installation with material supply, Supervision, Test & Commission.	-Installation Completed.
33.	Progressive Apparels Ind Ltd.  Contact Per Ref Mr. Hasan Managing director 01711748256	68/Y ,SagorikaRoad,Pahart oli ,Chittagong, Bangladesh	Fire Hydrantsystems Installation with material supply, Supervision, Test &Commission.	-Installation Completed.

## **Detail Engineering Electrical, Project List**

Electrical Safety Assessment: Under Banner of Uttaron Technologies

Assessors: Engr. Md. Mamorej Hossen

Sl.	Factory Name	Factory Address	Description of Job	Status of the
No			&Responsibility	project
1.	Envoy Textiles Ltd	Jamirdia, Bhaluka, Mymensingh, Dhaka Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 19 Feb 2014.
2.	Radisson Washing Plant Ltd	C-126, BSCIC Industrial Area, Tongi, Gazipur Dhaka Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 03 Jan 2014
3.	Opex Garments Ltd	H # 56/1, Block C Section 13, Mirpur, Dhaka Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 04 Dec 2013
4.	SMART JACKET (BD) LIMITED	Plot No - 11, 12 & 13, Roasd 5, Sector 1/A, CEPZ Chittagong Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 05 Dec 2013
5.	Opex Washing Plant Ltd	Opex Group Kanchpur, Sonargoan, Narayangonj Dhaka	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 15 Jan 2014
6.	ShehanSpecialized Textile Mills Ltd.	Plot #11-12, Sector #1/A, Road #5 CEPZ, Chittagong Chittagong Bangladesh	Initial Electrical Safety Assessment For ALLIANCE Assessor Electrical.	Report Completed on 01 Apr 2014
7.	Apollo Stickers Co	Plot 649, 650, DEPZ Road, Zirabo, Ashulia, Savar Dhaka Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 17 Dec 2013
8.	Radisson Apparels Ltd	C-125-126, BSCIC, I/A, Tongi, GazipurTongi, Gazipur Dhaka Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 03 Jan 2014
9.	Park (Bangladesh) Company Limited	Plot No. 7-11, Sector 01, KEPZ, North Patenga, Chittagong Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 05 Dec 2013
10.	Zaber&Zubair Fabrics Ltd	Pagar, Tongi, Gazipur Dhaka Bangladesh	Initial Electrical Safety Assessment For ALLIANCE. Assessor Electrical.	Report Completed on 20 May 2014

## **Electrical System Design:**

Design by: Engr. Md. Mamorej Hossen Checked by: Engr. AMM Mostafizur Rahman

Sl. No	Factory Name	Factory Address	Description of Job	Status of the project
11.	RSB Industrial Ltd.	Plot # 34-35, Sector # 4, CEPZ.	SLD & ELD	-Design Completed & Approved by ALLIANCE
12.	SIAM'S SUPERIOR LTD. (UNIT-2)	Plot # 7-9 Sector # 08, CEPZ, Chittagong, Bangladesh	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
13.	BD Designs Private Ltd.	Plot No. 48-49, Sector-3 Karnaphuli EPZ, Chittagong, Bangladesh	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
14.	CROWN MILLS (BD) LTD	Plot No. 17-19 & 36-38, Sector 2,CEPZ Chittagong	LPS	-Design Completed & Approved by ALLIANCE
15.	HKD International (CEPZ) LTD.	Plot # 49-55,Sector # 8, Road#05,CEPZ.	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
16.	Premier 1888 Ltd.	. 41-47 & 84, Sector # 7, EPZ, Chittagong Bangladesh	LPS	-Design Completed & Approved by ALLIANCE
17.	MZM (CEPZ) LTD.	Plot # 8-9, Sector # 2/A, CEPZ, Chittagong	SLD, ELD & LPS	-Design Completed & Approved by ACCORD
18.	HKD Outdoor Innovations Ltd	Plot # 45-50, Sector # 2, KEPZ, Chittagong, Bangladesh	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
19.	HELA CLOTHING BANGLADESH LTD.	Plot # 53, 54, 66, 67; Sector # 01, Karnaphuli EPZ, Chittagong,	SLD, ELD & LPS	-Design Completed & Approved by ACCORD
20.	SIAM'S SUPERIOR LTD. (UNIT-1).	Plot # 6-8 Sector # 01, CEPZ, Chittagong, Bangladesh	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
21.	Legacy Fashion Ltd.	BSCIC, Kalurghat, Chittagong, Bangladesh	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
22.	Anowara Fashion Ltd.	BSCIC, Kalurghat, Chittagong, Bangladesh	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE
23.	Familytex (BD) Limited.	Plot 47-48, Road 5, Sector 4, CEPZ, Chittagong	SLD, ELD & LPS	-Design Completed & Approved by ALLIANCE

	MAM APPAREL &	Tower, 3233/B,	SLD&ELD	-Design Completed &
24.	TEXTILES LTD,	Loharpool, Saraypara,		Approved by ALLIANCE
	MAM	Pahartali,Ctg		
	LHOTSE (BD)	Plot no- 60 & 61,	SLD, ELD & LPS	-Design Completed &
25.	LIMITED.	Sector-03, Karnaphuli		Approved by ALLIANCE
25.		Export Processing Zone		
		Chittagong, Bangladesh		
	SOS OUTFITTERS	PLOT NO. 33,	SLD, ELD & LPS	-Design Completed
26.	LTD.	SECTOR-3, KEPZ,		
		Chittagong.		
27.	NLZ (BD) Ltd.	CEPZ, Chittagong,	SLD, ELD & LPS	-Design Completed
27.		Bangladesh		
	PRM fashions Pvt	KEPZ,	SLD, ELD & LPS	-Designonprogress
28.	Ltd.	Chittagong,Bangladesh		

# Electrical system Execution, Supervision & Rectification, Test, Commissioning & Maintenance: LEAD by: Engr. Md. Mamorej Hossen

Sl. No	Factory Name	Factory Address	Description of Job	Status of the project
29.	RSB Industrial LTD	Plot # 34-35, Sector # 4, CEPZ.	SLD Execution, Supervision & Rectification, Test: Thermo graphic scan, ER, IR	-Design Completed & Approved by ALLIANCE
30.	SIAM'S SUPERIOR LTD. (UNIT-2)	Plot # 7-9 Sector # 08, CEPZ, Chittagong, Bangladesh	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
31.	BD Designs Private Ltd.	Plot No. 48-49, Sector-3 Karnaphuli EPZ, Chittagong,Bangladesh	& Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
32.	HKD International (CEPZ) LTD.	Plot # 49-55,Sector # 8, Road#05,CEPZ.	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
33.	CROWN MILLS (BD) LTD	Plot No. 17-19 & 36-38, Sector 2,CEPZ Chittagong	LPS Installation.	-Design Completed & Approved by ALLIANCE
34.	Premier 1888 Ltd.	. 41-47 & 84, Sector # 7, EPZ, Chittagong Bangladesh	LPS Installation.	-Design Completed & Approved by ALLIANCE

35.	MZM (CEPZ) LTD.	Plot # 8-9, Sector # 2/A, CEPZ, Chittagong	LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ACCORD
36.	HELA CLOTHING BANGLADESH LTD.	Plot # 53, 54, 66, 67; Sector # 01, Karnaphuli EPZ, Chittagong,	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ACCORD
37.	SIAM'S SUPERIOR LTD. (UNIT-1).	Plot # 6-8 Sector # 01, CEPZ, Chittagong, Bangladesh	& Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
38.	Legacy Fashion Ltd.	BSCIC, Kalurghat, Chittagong, Bangladesh	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
39.	Anowara Fashion Ltd.	BSCIC, Kalurghat, Chittagong, Bangladesh	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
40.	Familytex (BD) Limited.	Plot 47-48, Road 5, Sector 4, CEPZ, Chittagong	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
41.	MAM APPAREL & TEXTILES LTD, MAM	Tower, 3233/B, Loharpool, Saraypara, Pahartali,Ctg	SLD Execution, Supervision & Rectification, Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
42.	LHOTSE (BD) LIMITED.	Plot no- 60 & 61, Sector- 03, Karnaphuli Export Processing Zone Chittagong, Bangladesh	LPS installation Test:Thermo graphic scan, ER,IR	-Design Completed & Approved by ALLIANCE
43.	SOS OUTFITTERS LTD.	PLOT NO. 33, SECTOR-3, KEPZ, Chittagong.	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	- Work on progress
44.	NLZ Fashion Ltd.	CEPZ, Chittagong, Bangladesh	SLD Execution, Supervision & Rectification, LPS installation Test:Thermo graphic scan, ER,IR	- Work on progress